Support function list with CAT-iq router
for Panasonic CAT-iq Products

KX-TGQ500SL/400SL/200SL

Bland	Model name	Version	External call						Internal call		Advanced feature					
			Keypad dialing	Phonebook dialing	Outgoing list	Receive	Caller ID display	Call back from caller list	Call	Receive	High Quality Voice (HD Voice)	Multi-Line Telephone Call	Enhanced security	Call transfer	3-party conference	ECO Plus(No emission)
Swisscom	Internet Box2	-	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	Internet Box standard	-	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
FRITZ!Box	FRITZ!Box 7590	-	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 7560	6.83 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 7490	6.80 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 7390	6.80 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 7360	6.83 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 6840 LTE	6.84 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 5490	6.83 or later	✓	✓	✓(*1)	✓	✓	✓(*2)	✓	✓	✓	✓(*3)	✓	✓	✓(*1)	✓(*1)
	FRITZ!Box 7340	–	NOT compatible													
	FRITZ!Box 7330	–														
	FRITZ!Box 3490	–														
	FRITZ!Box 3390	–														
	FRITZ!Box 3370	–														
	FRITZ!Box 3272	–														

✓	Function is supported
✓(*1)	This function is option feature of CAT-iq2.0. This function might NOT be supported depending on router version.
✓(*2)	Caller list includes Accepted Calls, Missed Calls and All Incoming Calls. The All Incoming Calls list might NOT be supported depending on router version.
✓(*3)	Multi-Line Telephone Call is available accoring to router specification and contract of network service provider.
X	Function is NOT supported
NOT compatible	FRITZ!Box does NOT support compatibility with Panasonic CAT-iq cordless phone.

<How to confirm Fritz!box model name >

ex) FRITZ!Box 7490
The 7490 is a model name.

<Trouble shooting>

If the specified function in this compatibility list doesn't work correctly,
Please confirm your FRITZ!Box version.
It may be necessary to update software of your FRITZ!Box and reregister your handset to FRITZ!Box.